

Inspection Photos
Location Name: MALO 9-20
Location ID: 330637



Photo 1 – Pumping Unit



Photo 2 – Tank Battery



Inspection Photos
Location Name: MALO 9-20
Location ID: 330637



Photo 3 – Stained Soil at Gas Engine and Trash




Photo 4 – Stained Soil inside Treater Shed

Inspection Photos
Location Name: MALO 9-20
Location ID: 330637



Photo 5 – Unused Chemical Tanks and Containment