

**Inspection Photos**  
**Location Name: Divide Creek Unit**  
**Location ID: 322310**  
**Inspection Date: September 4, 2019**



**Photo #1 – Aerial view of the location (GISOnline Maps).**



**Photo #2 – Location sign.**



**Inspection Photos**  
**Location Name: Divide Creek Unit**  
**Location ID: 322310**  
**Inspection Date: September 4, 2019**



**Photo #3 – View of active drip coming from the 2000 BBL produced water AST.**



**Photo #4 – View of location fencing.**

**Inspection Photos**  
**Location Name: Divide Creek Unit**  
**Location ID: 322310**  
**Inspection Date: September 4, 2019**



**Photo #5 – View of location fencing.**



**Photo #6 – View of unmarked flowline.**