



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Sep 13, 2019 4:48:43 PM MDT
Server Receive Date:	Sep 13, 2019 4:50:45 PM MDT
Reference Number:	20190913-18117166180
Location:	557 Airpark Dr, Durango, CO 81303, USA Sep 13, 2019 4:49:56 PM MDT [ <a href="#">View Map</a> ]

## Information

Name	colen@horizonenvservices.com
Date	Sep 13, 2019
Well Name	MANKINS, HOWARD GAS UNIT 3
API Number	50670870900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Other

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

sign

Photo of third corrective action completed



Completed work description of corrective action 3  
Photo of fourth corrective action completed

treated noxious weeds



Completed work description  
Completed work description of corrective action 4  
Summary of all work completed

treated noxious weeds  
treated noxious weeds  
treated noxious weeds in reclamation area