

Inspection Photos

Loc#324314

Operator: Laramie

Inspection Number: 692401347

Inspection Date: 9/6/19





Photo#1:
Overview of Location to Southwest.

September 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie CC Loc#324314



Photo#2:
One of two Drains located at West edge of Pad



Photo#3:
One of two Drains located at West edge of Pad.

September 6, 2019




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie CC Loc#324314



Photo#4:
Views of un-stabilized overly Steep Fill Slopes.



Photo#5:
Views of un-stabilized overly Steep Fill Slopes.

September 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie CC Loc#324314