

# Inspection Photos

Location Name: Waag South SESW Pad #1  
Location ID: 439204



Colorado Oil and Gas Conservation Commission  
40.55364, -104.70774, 1468.4m, 327°  
Sep 16, 2019 12:30:12

Photo 1: Location Sign



Colorado Oil and Gas Conservation Commission  
40.55362, -104.70771, 1467.6m, 27°  
Sep 16, 2019 12:30:25

Photo 2: Location

**Inspection Photos**  
**Location Name: Waag South SESW Pad #1**  
**Location ID: 439204**



**Photo 3: Tank Battery**



**Photo 4: Unused equipment**

**Inspection Photos**  
**Location Name: Waag South SESW Pad #1**  
**Location ID: 439204**



**Photo 5: Unused Equipment, disconnected separator**



**Photo 6: Unused Equipment**

**Inspection Photos**  
**Location Name: Waag South SESW Pad #1**  
**Location ID: 439204**



**Photo 7: Unused equipment, storage of unknown substance in bucket**

**Photo 8: Storage of unknown substance in bucket**

**Inspection Photos**  
**Location Name: Waag South SESW Pad #1**  
**Location ID: 439204**



**Photo 9: Unused equipment**