

Inspection Photos
Location Name: Federal 6-13
Location ID: 322392
Inspection Date: September 10, 2019



Photo #1 – Aerial view of the location. The black drop represent the location of the open Spill ID 440877, the red cross represents the open Remediation Project 11306 and the green square represent open Pit ID 112108 (GISOnline Maps).



Photo #2 – Location sign.

Inspection Photos
Location Name: Federal 6-13
Location ID: 322392
Inspection Date: September 10, 2019



Photo #3 – View of the landfarm looking southeast.



Photo #4 – View of the landfarm looking southwest.

Inspection Photos
Location Name: Federal 6-13
Location ID: 322392
Inspection Date: September 10, 2019



Photo #5 – View of the excavation looking west.



Photo #6 – View of the excavation looking south.

Inspection Photos
Location Name: Federal 6-13
Location ID: 322392
Inspection Date: September 10, 2019



Photo #7 – View of the horizontal separators located west of the location.



Photo #8 – View of unused equipment.

Inspection Photos
Location Name: Federal 6-13
Location ID: 322392
Inspection Date: September 10, 2019



Photo #9 – View of stained soil beneath the compressor unit.



Photo #10 – View of inadequate berms around the 100 BBL AST.