

Inspection Photos
Location Name: Leffler 26Q-HZ Pad
Location ID: 426699



Photo 1: Location



Photo 2: Tank Battery

Inspection Photos
Location Name: Leffler 26Q-HZ Pad
Location ID: 426699



Photo 3: Trash removed



Photo 4: Bird nest removed

Inspection Photos
Location Name: Leffler 26Q-HZ Pad
Location ID: 426699



Colorado Oil and Gas Conservation Commission
40.53905, -104.74289, 1464.2m, 324°
Sep 17, 2019 14:26:59



Colorado Oil and Gas Conservation Commission
40.539, -104.74343, 1464.0m, 111°
Sep 17, 2019 14:29:32

Photo 5: Unused secondary containment device on location

Photo 6: Erosion to south end of location