

Inspection Photos
Operator: BP America
Location/API #: 067-08334
Date: 9-10-2019



Photo 1. View of the project area from the southwestern edge facing center.



Photo 2. View of the southern fill slope from the southwestern edge facing eastward.



Photo 3. View of Canada thistles within the southern project area.



Photo 4. View of debris within the eastern project area.



Photo 5. View of reference area east of project area, comprised of grassland field vegetation such as crested wheatgrass and smooth brome.