

Ant Hill Unit 19-12
API: 05-103-10294
Inspection: 679705487



40.13332, -108.21046, 6021.8ft, 32°
09/17/2019 02:43:35 PM

Photo 1. Location.

Ant Hill Unit 19-12
API: 05-103-10294
Inspection: 679705487



Photo 2. Stained gravel next to water tank.



Photo 3. Stained gravel next to water tank.

Ant Hill Unit 19-12
API: 05-103-10294
Inspection: 679705487



Photo 4. Battery sign.