

**Inspection Photos**  
**Location Name: UPRR 42 Pan Am G1, G2, G3, G4 TB**  
**Location ID: 333006**



**Photo #1 TB sign**



**Photo #2 TB**



**Inspection Photos**  
**Location Name: UPRR 42 Pan Am G1, G2, G3, G4 TB**  
**Location ID: 333006**




**Photo #3 Vert. sep**




**Photo #4 unused, unmarked riser no LOTO**



**Inspection Photos**  
**Location Name: UPRR 42 Pan Am G1, G2, G3, G4 TB**  
**Location ID: 333006**



**Photo #5 unused, unmarked riser no LOTO**



**Photo #6 unused, unmarked riser no LOTO**

## Inspection Photos

Location Name: UPRR 42 Pan Am G1, G2, G3, G4 TB

Location ID: 333006



**Photo #7 Vert. sep. house in disrepair**



**Photo #8 Horiz. heated sep.**



**Inspection Photos**  
**Location Name: UPRR 42 Pan Am G1, G2, G3, G4 TB**  
**Location ID: 333006**



**Photo #9 Gas meter run**



**Photo #10 Produced water tank.**