

Location:	Smith/Halverson
Line:	Oil Dump
Technicians:	Cody Baylis
Date	9/12/2019
Time	Pressure (PSI)
10:26:10 AM	0.1
10:26:40 AM	0.1
10:27:10 AM	0.1
10:27:40 AM	0.1
10:28:10 AM	0.2
10:28:40 AM	0.2
10:29:10 AM	0.2
10:29:40 AM	3.5
10:30:10 AM	47.1
10:30:40 AM	47.1
10:31:10 AM	47.1
10:31:40 AM	47
10:32:10 AM	47
10:32:40 AM	47
10:33:10 AM	47
10:33:40 AM	47
10:34:10 AM	47
10:34:40 AM	47
10:35:10 AM	47
10:35:40 AM	47
10:36:10 AM	47
10:36:40 AM	47
10:37:10 AM	47
10:37:40 AM	47
10:38:10 AM	47
10:38:40 AM	47
10:39:10 AM	47
10:39:40 AM	47
10:40:10 AM	46.9
10:40:40 AM	46.9
10:41:10 AM	46.9
10:41:40 AM	46.9
10:42:10 AM	46.9
10:42:40 AM	46.9
10:43:10 AM	46.9
10:43:40 AM	46.9
10:44:10 AM	46.9
10:44:40 AM	46.9
10:45:10 AM	46.9
10:45:40 AM	46.9
10:46:10 AM	46.8
10:46:40 AM	46.8

10:47:10 AM	46.8
10:47:40 AM	46.8
10:48:10 AM	46.8
10:48:40 AM	46.7
10:49:10 AM	46.7
10:49:40 AM	46.7
10:50:10 AM	46.7
10:50:40 AM	46.7
10:51:10 AM	46.7
10:51:40 AM	46.7
10:52:10 AM	46.7
10:52:40 AM	46.7
10:53:10 AM	46.7
10:53:40 AM	46.7
10:54:10 AM	46.7
10:54:40 AM	46.7
10:55:10 AM	46.7
10:55:40 AM	46.7
10:56:10 AM	46.6
10:56:40 AM	46.6
10:57:10 AM	46.6
10:57:40 AM	46.6
10:58:10 AM	46.6
10:58:40 AM	46.6
10:59:10 AM	46.6
10:59:40 AM	46.6
11:00:10 AM	46.6
11:00:40 AM	46.6
11:01:10 AM	46.6
11:01:40 AM	46.6
11:02:10 AM	46.6
11:02:40 AM	46.6
11:03:10 AM	46.5
11:03:40 AM	46.5
11:04:10 AM	46.5
11:04:40 AM	46.5
11:05:10 AM	46.5
11:05:40 AM	46.5
11:06:10 AM	46.5
11:06:40 AM	21.5
11:07:10 AM	2.2
11:07:40 AM	0.8
11:08:10 AM	0.5
11:08:40 AM	0.9
11:09:10 AM	1.1
11:09:40 AM	1.1
11:10:10 AM	0.5

Pass/Fail

% loss over 30 minutes	1.27%	Less than 10%	Yes		
% loss in last 5 minutes	0.21%	Less than 1%	Yes		Pass

