

Location:	Smith/Halverson
Line:	Water Dump
Technicians:	Cody Baylis
Date	9/12/2019
Time	Pressure (PSI)
11:07:40 AM	0.8
11:08:10 AM	0.5
11:08:40 AM	0.9
11:09:10 AM	1.1
11:09:40 AM	1.1
11:10:10 AM	0.5
11:10:40 AM	1.4
11:11:10 AM	46
11:11:40 AM	46
11:12:10 AM	46.1
11:12:40 AM	46.1
11:13:10 AM	46.1
11:13:40 AM	46.1
11:14:10 AM	46.2
11:14:40 AM	46.2
11:15:10 AM	46.2
11:15:40 AM	46.2
11:16:10 AM	46.2
11:16:40 AM	46.2
11:17:10 AM	46.2
11:17:40 AM	46.2
11:18:10 AM	46.2
11:18:40 AM	46.2
11:19:10 AM	46.2
11:19:40 AM	46.2
11:20:10 AM	46.2
11:20:40 AM	46.2
11:21:10 AM	46.2
11:21:40 AM	46.2
11:22:10 AM	46.1
11:22:40 AM	46.1
11:23:10 AM	46.1
11:23:40 AM	46.1
11:24:10 AM	46.1
11:24:40 AM	46.1
11:25:10 AM	46.1
11:25:40 AM	46.1
11:26:10 AM	46
11:26:40 AM	46
11:27:10 AM	46
11:27:40 AM	46
11:28:10 AM	46

11:28:40 AM	46
11:29:10 AM	46
11:29:40 AM	46
11:30:10 AM	46
11:30:40 AM	46
11:31:10 AM	46
11:31:40 AM	46
11:32:10 AM	46
11:32:40 AM	46
11:33:10 AM	46
11:33:40 AM	46
11:34:10 AM	46
11:34:40 AM	46
11:35:10 AM	46
11:35:40 AM	46
11:36:10 AM	46
11:36:40 AM	46
11:37:10 AM	46
11:37:40 AM	46
11:38:10 AM	46
11:38:40 AM	46
11:39:10 AM	46
11:39:40 AM	45.9
11:40:10 AM	46
11:40:40 AM	46
11:41:10 AM	46
11:41:40 AM	46
11:42:10 AM	45.9
11:42:40 AM	45.9
11:43:10 AM	45.9
11:43:40 AM	45.9
11:44:10 AM	45.9
11:44:40 AM	45.9
11:45:10 AM	45.9
11:45:40 AM	45.9
11:46:10 AM	45.9
11:46:40 AM	45.9
11:47:10 AM	45.9
11:47:40 AM	0.4
11:48:10 AM	0.7
11:48:40 AM	0.7
11:49:10 AM	0.7
11:49:40 AM	0.7
11:50:10 AM	0.7

Pass/Fail

% loss over 30 minutes	0.65%	Less than 10%	Yes		
% loss in last 5 minutes	0.00%	Less than 1%	Yes		Pass

