

Location:	Halverson Flowline
Line:	Well to Separator
Technicians:	Cody Baylis
Date	9/9/2019
Time	Pressure (PSI)
10:22:10 PM	0
10:22:40 PM	0
10:23:10 PM	0
10:23:40 PM	0
10:24:10 PM	1.3
10:24:40 PM	13.3
10:25:10 PM	38.7
10:25:40 PM	57.7
10:26:10 PM	68.6
10:26:40 PM	75.9
10:27:10 PM	89.5
10:27:40 PM	95.7
10:28:10 PM	95.4
10:28:40 PM	95.2
10:29:10 PM	95.2
10:29:40 PM	95
10:30:10 PM	95
10:30:40 PM	94.9
10:31:10 PM	94.9
10:31:40 PM	94.8
10:32:10 PM	94.8
10:32:40 PM	94.8
10:33:10 PM	94.8
10:33:40 PM	94.7
10:34:10 PM	94.7
10:34:40 PM	94.7
10:35:10 PM	94.7
10:35:40 PM	94.6
10:36:10 PM	94.6
10:36:40 PM	94.6
10:37:10 PM	94.6
10:37:40 PM	94.5
10:38:10 PM	94.5
10:38:40 PM	94.5
10:39:10 PM	94.5
10:39:40 PM	94.5
10:40:10 PM	94.5
10:40:40 PM	94.4
10:41:10 PM	94.5
10:41:40 PM	94.4
10:42:10 PM	94.4
10:42:40 PM	94.3

10:43:10 PM	94.4
10:43:40 PM	94.3
10:44:10 PM	94.4
10:44:40 PM	94.3
10:45:10 PM	94.3
10:45:40 PM	94.3
10:46:10 PM	94.3
10:46:40 PM	94.3
10:47:10 PM	94.3
10:47:40 PM	94.2
10:48:10 PM	94.3
10:48:40 PM	94.2
10:49:10 PM	94.2
10:49:40 PM	94.2
10:50:10 PM	94.2
10:50:40 PM	94.2
10:51:10 PM	94.2
10:51:40 PM	94.2
10:52:10 PM	94.2
10:52:40 PM	94.1
10:53:10 PM	94.2
10:53:40 PM	94.1
10:54:10 PM	94.2
10:54:40 PM	94.1
10:55:10 PM	94.1
10:55:40 PM	94.1
10:56:10 PM	94.1
10:56:40 PM	94.1
10:57:10 PM	94.1
10:57:40 PM	94
10:58:10 PM	94.1
10:58:40 PM	94
10:59:10 PM	94
10:59:40 PM	94
11:00:10 PM	94
11:00:40 PM	94
11:01:10 PM	94
11:01:40 PM	94
11:02:10 PM	94
11:02:40 PM	94
11:03:10 PM	94
11:03:40 PM	0
11:04:10 PM	0
11:04:40 PM	0
11:05:10 PM	0.5
11:05:40 PM	0.8

Pass/Fail

% loss over 30 minutes	1.05%	Less than 10%	Yes		
% loss in last 5 minutes	0.11%	Less than 1%	Yes		Pass

