

Inspection Photos
Operator: BP America
Location/API #: 067-08213
Date: 9-10-2019



Photo 1. View of the project area from the northwestern edge facing center.



Photo 2. View of the western fill slope from the northwestern edge facing southward. Revegetation is progressing largely with western wheatgrass, intermediate wheatgrass, crested wheatgrass, and smooth brome.



Photo 3. View of musk thistles within the interim reclamation area.



Photo 4. View of reference area vegetation facing westward. Vegetation is comprised of sagebrush shrubland.