

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-08111
Date: 9-11-2019



Photo 1. View of remediation area within the western project area facing northwestward. It does not appear that revegetation has been conducted here.



Photo 2. View of remediation area within the western project area facing southward. Area needs revegetation.