

Inspection Photos  
Location: 057-06625  
Inspection Date: 9/12/2019  
Photos taken by Kris Neidel



Photo #1 looking west. Truck is parked just off the west side of the pad. It is planned to use the cuttings in the fill of this side of pad.

Inspection Photos  
Location: 057-06625  
Inspection Date: 9/12/2019  
Photos taken by Kris Neidel



Photo #2 looking to the south west. Surface cuttings are visible in background.

Inspection Photos  
Location: 057-06625  
Inspection Date: 9/12/2019  
Photos taken by Kris Neidel



Photo #3 piled soil on north side of cuttings management area.

