

Anderson 17-4
API: 05-103-08552
Inspection: 679705523



Photo 1. Location.

Anderson 17-4
API: 05-103-08552
Inspection: 679705523



Photo 2. Pump jack



Anderson 17-4
API: 05-103-08552
Inspection: 679705523



Photo 3. Pump jack casing gas tank.

Photo 4. Pump jack casing gas tank valve.

Gas venting

Anderson 17-4
API: 05-103-08552
Inspection: 679705523



Photo 5. Bag on pump jack casing gas tank valve.



Photo 6. Stained soil at crude off loading valve.