

Inspection Photos
Location Name: Andrews 26 Production Facility
Location ID: 430074



Colorado Oil and Gas Conservation Commission
40.54106, -104.63531, 1467.7m, 75°
Sep 18, 2019 12:15:23

Photo 1: Location



Colorado Oil and Gas Conservation Commission
40.54147, -104.63468, 1470.8m, 71°
Sep 18, 2019 12:16:16

Photo 2: Tank Battery Sign

Inspection Photos
Location Name: Andrews 26 Production Facility
Location ID: 430074



Photo 3: Tank Battery



Photo 4: No BBLs on H2O tank

Inspection Photos
Location Name: Andrews 26 Production Facility
Location ID: 430074



Photo 5: 2 unused (LOTO) risers