

Inspection Photos
Location Name: Harper USX EE 27 PAD
Location ID: 423538



Photo 1: Battery Sign



Photo 2: Location



Inspection Photos
Location Name: Harper USX EE 27 PAD
Location ID: 423538



Photo 3: Unused equipment in gas meter house



Photo 4: Unused equipment near gas meter house

