

Final Reclamation Inspection

September 17, 2019

Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC - #10261

Location ID: 306743

Inspection Document #: 697500608

Weld County, CO

SWNW Section 31 T7N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HESTER #31-23
Location ID: 306743



Photo 1. Photo taken from the well location, facing West. Photo illustrates Operator has failed to perform Final Reclamation activities at the well location, as there is no apparent vegetative growth which also has not been properly contoured. This PA well location is outside of the Hester Farms II 31-H Pad disturbance area.

Inspection Photos
Location Name: HESTER #31-23
Location ID: 306743



Photo 2. Photo taken from the well location, facing North. Photo illustrates unused equipment at the well location.