

Inspection Photos

09/20/2019

Operator: NOBLE ENERGY INC - 100322

Location ID: 422755

Weld County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos
Operator Name: NOBLE ENERGY INC - 100322
Location ID: 422755



Photo 1: Photo taken from the access road, facing east. Photo shows area where noxious weeds (Canada thistle) was documented in previous inspections. Photo shows operator appears to have conducted mowing operations. Mowing operations insufficient as individual weeds with mature seed heads remain (arrow).



Photo 2: Continued from photo 1. Photo shows Canada thistle rosettes remaining along the access road. Operator has failed to conduct sufficient noxious weed management to properly manage/remove weeds.

Inspection Photos
Operator Name: NOBLE ENERGY INC - 100322
Location ID: 422755



Photo 3: Continued from photo 1. Photo shows Canada thistle remaining along the access road. Operator has failed to conduct sufficient noxious weed management to properly remove weeds.



Photo 4: Continued from photo 3. Photo shows Canada thistle rosettes remaining along the access road. Operator has failed to conduct sufficient noxious weed management to properly manage/remove weeds.