

Inspection Photos
Location Name: State 26-2
Location ID: 327091



Photo 1 – Wellhead and Pumping Unit, weeds around well



Photo 2 – Tank Battery; weeds actively growing in and around berm

Inspection Photos
Location Name: State 26-2
Location ID: 327091



Photo 3 – Fence at wellhead is in disrepair



Photo 4 – Wellhead Sign; does not reflect current Operator, no Emergency Contact #.

Inspection Photos
Location Name: State 26-2
Location ID: 327091



Photo 5 – Tank Battery Sign; does not reflect current Operator, no Emergency Contact #.



Photo 6 – Weeds actively growing at Separator

Inspection Photos
Location Name: State 26-2
Location ID: 327091



Photo 7 – Weeds actively growing at Gas Meter House



Photo 8 – Unused Motor Oil container on south side of Production Tank

Inspection Photos
Location Name: State 26-2
Location ID: 327091



**Photo 9 – Rock is wedged between vault and netting,
creating a potential opening for Wildlife.**