

Inspection Photos
Location Name: Federal 6-3
Location ID: 322387
Inspection Date: September 10, 2019



Photo #1 – Aerial view of the location. The black drop represent Spill ID 438537 and the white square represent the unknown status pits that are associate with the location.



Photo #2 – Location sign.

Inspection Photos
Location Name: Federal 6-3
Location ID: 322387
Inspection Date: September 10, 2019



Photo #3 – View of the methanol day tank sign.



Photo #4 – View of vegetation on location.



Inspection Photos
Location Name: Federal 6-3
Location ID: 322387
Inspection Date: September 10, 2019



Photo #7 – View of the berms around the 60 bbl produced water tank.



Photo #8 – View of the 60 bbl produced water tank.



Inspection Photos
Location Name: Federal 6-3
Location ID: 322387
Inspection Date: September 10, 2019



Photo #9 – View of the 5 bbl produced water tank.



Photo #10 – View of the uncapped flowline on the 60 bbl produced water tank.

