

Inspection Photos

API#103-09164

Operator: Bayswater

Inspection Number: 692401234

Inspection Date: 7/31/19





Photo#1:
Overview of Location; desirable vegetation is establishing

July 31, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Bayswater Emerald 284 PA API#103-09164



Photo#2:
Establishment of Halogeton on site.

July 31, 2019



Photo#3:
Cheat grass and Penny cress on site.

July 31, 2019