

Final Reclamation Inspection

September 17, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 319090

Inspection Document #: 697500616

Weld County, CO

NENW Section 26 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BUXMAN, D. #1-26
Location ID: 319090



Photo 1. Photo taken from the well location entrance point, facing South. COGCC staff could not make a full assessment due to crop height and density, as the location was ~500' further south.

Inspection Photos
Location Name: BUXMAN, D. #1-26
Location ID: 319090



Photo 2. Photo taken from the well location entrance point, facing West. Photo illustrates the Operator has failed to remove the culvert. There is an access point for this crop field ~600 feet to the west of this point. This access point is no longer in use and was used for oil and gas operations.