

Inspection Photos

Loc#336050

Operator: Chevron

Inspection Number: 692401363

Inspection Date: 8/20/19





Photo#1:

Overview of Location to North; Areas no longer needed for Use have not been Reclaimed.

August 20, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron Loc#336050



Photo#2:

Overview of Location to South; Areas no longer needed for Use have not been Reclaimed

August 20, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron Loc#336050



Photo#3:
Google Earth 2016 aerial of Location; unknown stockpile indicated by Pink Pin.

August 20, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron Loc#336050



Photo#4:
COGCC 2009 maps aerial of Location; unknown stockpile indicated by arrow.

August 20, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron Loc#336050