

9N53K32



00238885

RCC

LEASE INSPECTION FORM

Operator

Baney

Date

May 30 1985

Field

Mid Hope East

Lease Name & No.

Tuttsell C-1

County

Logan

Tank Battery No.

9N53K32

Location

NESW 32-9N-53W

Legal Description

Type of Inspection

Reg Pit

Water Inflow

(Bbls. Per Day)

RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)

Type of Tank

SKIM TANK

Pit No. 1

Skim 10X10 - Wire Cover - 100% Cover 1' Deep

Pit No. 2

60X60 - Clear 2' Deep

Pit No. 3

ADDITIONAL PITS

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety Conditions, Etc.)

OK

RECOMMENDED ACTION (If Required)

INSPECTOR

D. Becknell