

**Inspection Photos**  
**Location Name: Elkhorn Company B #7**  
**Location ID: 318599**



**Photo #1 WH sign**



**Photo #2 PU**

Inspection Photos  
Location Name: Elkhorn Company B #7  
Location ID: 318599



Photo #3 Stained soil around WH



Photo #4 Debris/weeds: dead weeds removed from around electric panel

**Inspection Photos**  
**Location Name: Elkhorn Company B #7**  
**Location ID: 318599**



**Photo #5 Debris/weeds: Dead weeds around location**

**Photo #6 Debris/weeds: dead weeds around location**