

Inspection Photos
Location Name: Hoff 6-62-15-1H
Location ID: 421423



Photo 1 – Pumping Unit, weeds around well



Photo 2 – Tank Battery

Inspection Photos
Location Name: Hoff 6-62-15-1H
Location ID: 421423



Photo 3 – Unused Methanol Tank/Pump on the Northeast side of location



Photo 4 – Unused equipment in Treater shed and Stained Soil

Inspection Photos
Location Name: Hoff 6-62-15-1H
Location ID: 421423




Photo 5 – Unused equipment in Treater shed



Photo 6 – Stained Soil at the dumps inside Treater shed