

# Inspection Photos

API: 05-071-06811

Operator: ARP PRODUCTION COMPANY

WAPITI OPERATING LLC

Inspection Date: 9/23/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06811 | Date: 9/23/2019

## Inspection Photos



**Photo 1.** There is List B noxious weeds growing at the fill slope of the location.  
(Musk thistle shown in photo)



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06811 | Date: 9/23/2019

## Inspection Photos



**Photo 2.** Facing toward the pumpjack at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06811 | Date: 9/23/2019