

Inspection Photos  
Location Name: Meyer F-1  
Location ID: 318940



Photo 1 – Weeds growing around Tank Battery berm



Photo 2 – Weeds at Heater Treater; unused equipment

**Inspection Photos**  
**Location Name: Meyer F-1**  
**Location ID: 318940**



**Photo 3 – Trash South East of Pumping Unit**



**Photo 4 – Weeds at Pumping Unit, Unused Equipment**

**Inspection Photos**  
**Location Name: Meyer F-1**  
**Location ID: 318940**



**Photo 5 – Open well bore, needs Nightcap or Cut and Capped**