

Inspection Photos

Loc#336051

Operator: Chevron

Inspection Number: 692401368

Inspection Date: 8/21/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southwest, from reclaimed access road into Location.

August 21, 2019



Photo#2:


View of Location to West over establishing vegetation; weeds are darker plants in foreground and on reclaimed slope.

August 21, 2019



Photo#3:
Weed establishment on reclaimed access road area.

August 21, 2019



Photo#4:

Tamarisk tree on road that runs along Northeast side of Location.

August 21, 2019