

Inspection Photos
Location Name: Steve J Pad
Location ID: 333001




Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: Steve J Pad
Location ID: 333001



Photo 3: Wellhead Sign



Photo 4: Wellhead

Inspection Photos
Location Name: Steve J Pad
Location ID: 333001



Colorado Oil and Gas Conservation Commission
40.39909, -104.82191, 1494.0m, 328°
Sep 24, 2019 13:33:24

Photo 5: Wellhead Sign



Colorado Oil and Gas Conservation Commission
40.39911, -104.82191, 1492.8m, 162°
Sep 24, 2019 13:33:33

Photo 6: Wellhead

Inspection Photos
Location Name: Steve J Pad
Location ID: 333001



Colorado Oil and Gas Conservation Commission
40.39921, -104.82252, 1493.8m, 288°
Sep 24, 2019 13:37:09

Photo 7: Tank Battery Sign



Colorado Oil and Gas Conservation Commission
40.39921, -104.82214, 1493.8m, 309°
Sep 24, 2019 13:37:32

Photo 8: Location

Inspection Photos
Location Name: Steve J Pad
Location ID: 333001



Photo 9: Tank Battery



Photo 10: Load out bucket with hole

Inspection Photos
Location Name: Steve J Pad
Location ID: 333001



Photo 11: Erosion



Photo 12: Erosion

Inspection Photos
Location Name: Steve J Pad
Location ID: 333001



Photo 13: Erosion



Photo 14: Disconnected gas meter houses