

Inspection Photos

API: 05-071-07386

Operator: ARP PRODUCTION COMPANY
WAPITI OPERATING LLC

Inspection Date: 9/23/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07386 | Date: 9/23/2019

Inspection Photos



Photo 1. Gravel has been spread along the access road. Rock check dams are installed. Some of which are filled in with sediment and need maintenance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07386 | Date: 9/23/2019

Inspection Photos



Photo 2. There is List B noxious weeds growing along the main & access road to the location. (Canada thistle shown in photo)

Corrective action was not performed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07386 | Date: 9/23/2019

Inspection Photos



Photo 3. There is List B noxious weeds growing along the main & access road to the location. (Canada thistle shown in photo)

Corrective action was not performed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07386 | Date: 9/23/2019

Inspection Photos



Photo 4. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07386 | Date: 9/23/2019