

WELL SITE INSPECTION



00216262

OPERATOR Dambe Co.

DATE 7/14/86

WELL NAME # 33-1 MAC FARRANE

COUNTY JACKSON

RIG Bu H #3

LEGAL NEW S33 T7N R79W

SURFACE CASING _____ SIZE _____ DEPTH _____ DATE _____

CEMENT VOLUME _____ RETURNS _____ WOC _____

PROBABLE FOX HILLS DEPTH _____

MUD PITS _____

DISPOSAL _____

PRODUCTION STRING _____ SIZE _____ DEPTH _____

STAGED _____ CBL CHECKED _____

SQUEEZE _____ FRAC JOB _____

BATTERY _____ SIGN _____

SITE INSPECTION AFTER DRILLING Dambe @ 400+ Feet.

Have 504' of Surface to Ser.

Spud on 7/13/86

Very CLEAR Rig - well kept.

DIRECTIONS _____

ACTION _____

ENGINEER R. NACLAVER

