

Inspection Photos
Location Name: Reubel 1-1 Pit
Location ID 119210



Photo 1 – Location photo

Photo 2 – Location photo; cement produced water vault on site

Inspection Photos
Location Name: Reubel 1-1 Pit
Location ID 119210



Photo 3 – Location photo



Photo 4 – Location photo

Inspection Photos
Location Name: Reubel 1-1 Pit
Location ID 119210



Photo 5 – Stained soil at separator



Photo 6 – Unmarked/inactive flowline risers located between tanks and separator

Aerial Imagery
Location Name: Reubel 1-1 Pit
Location ID 119210




Photo 7 – 1993 aerial imagery



Aerial Imagery
Location Name: Reubel 1-1 Pit
Location ID 119210



Photo 8 – 2002 aerial imagery



Aerial Imagery
Location Name: Reubel 1-1 Pit
Location ID 119210



Photo 9 – 2018 aerial imagery

