

Inspection Photos
Location Name: North Quebec Pits
Facility ID 113821 & 114290



Photo 1 – Battery Sign



Photo 2 – Location photo

Inspection Photos
Location Name: North Quebec Pits
Facility ID 113821 & 114290



Photo 3 – Location photo; fiberglass produced water tank on site



Photo 4 – Berms around tanks need repair

Inspection Photos
Location Name: North Quebec Pits
Facility ID 113821 & 114290



Photo 5 – Berms around tanks in disrepair



Photo 6 – Berms around tanks in disrepair

Inspection Photos
Location Name: North Quebec Pits
Facility ID 113821 & 114290



Photo 7 – Stained soil outside tank berms



Photo 8 – Stained soil under separator

Aerial Imagery
Location Name: North Quebec Pits
Facility ID 113821 & 114290



Photo 9 – 1993 aerial imagery



Aerial Imagery
Location Name: North Quebec Pits
Facility ID 113821 & 114290



Photo 10 – 2002 aerial imagery

Aerial Imagery
Location Name: North Quebec Pits
Facility ID 113821 & 114290



Photo 11 – 2018 aerial imagery