

Inspection Photos  
Location Name: Guthrie 1&2 Pit  
Facility ID 113810



Photo 1 – Tank Battery Sign; fiberglass produced water tank on site



Photo 2 – Location photo



**Inspection Photos**  
**Location Name: Guthrie 1&2 Pit**  
**Facility ID 113810**



**Photo 3 – Weeds on berms surrounding tanks**



**Photo 4 – Stained soil at load out**

**Inspection Photos**  
**Location Name: Guthrie 1&2 Pit**  
**Facility ID 113810**



**Photo 5 – Stained soil under crude oil tank valve**



**Photo 6 – Location photo**

Inspection Photos  
Location Name: Guthrie 1&2 Pit  
Facility ID 113810



Photo 7 – Location photo



Photo 8 – Location photo


**Aerial Imagery**  
**Location Name: Guthrie 1&2 Pit**  
**Facility ID 113810**



**Photo 9 – 1993 aerial imagery**




**Aerial Imagery**  
**Location Name: Guthrie 1&2 Pit**  
**Facility ID 113810**



**Photo 10 – 2002 aerial imagery**



**Aerial Imagery**  
**Location Name: Guthrie 1&2 Pit**  
**Facility ID 113810**



**Photo 11 – 2018 aerial imagery**

