

Inspection Photos
Location Name: Tateyama 15U-434
Location ID: 432487



Photo 1: Pumpjack Sign



Photo 2: Pumpjack

Inspection Photos
Location Name: Tateyama 15U-434
Location ID: 432487



Photo 3: Tank Battery



Photo 4: Location

Inspection Photos
Location Name: Tateyama 15U-434
Location ID: 432487



Photo 5: Tank Battery



Photo 6: Separator not anchored

Inspection Photos
Location Name: Tateyama 15U-434
Location ID: 432487



Photo 7: Unused Risers