

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402150683

Date Received:
08/20/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1310 W SAM HOUSTON PKWY N

City: HOUSTON State: TX Zip: 77043

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Randy Madison

Phone

575-445-6706

Email

rmadison@wapitienergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901034

Inspection Date: 07/19/2019

FIR Submit Date: 07/22/2019

FIR Status: _____

Inspected Operator Information:

Company Name: ARP PRODUCTION COMPANY LLC

Company Number: 10471

Address: 425 HOUSTON STREET SUITE 300

City: FORTH WORTH State: TX Zip: 76102

LOCATION - Location ID: 420752

Location Name: VPR C Number: 204 WDW County: LAS ANIMAS

Qtrqr: SESE Sec: 1 Twp: 35S Range: 67W Meridian: 6

Latitude: 37.022810 Longitude: -104.832550

FACILITY - API Number: 05-071- -00 Facility ID: 420756

Facility Name: VPR C Number: 204 WDW

Qtrqr: SESE Sec: 1 Twp: 35S Range: 67W Meridian: 6

Latitude: 37.022810 Longitude: -104.832550

CORRECTIVE ACTIONS:

1 ☒ CA# 128367

Corrective Action: Comply with Rule 1003.f.
Provide a plan for ongoing weed control.

Date: 08/01/2019

Response: CA COMPLETED

Date of Completion: 08/19/2019

Operator Comment: See attached weed plan created by a professional out of Trinidad CO. We choose a local professional so he
knowledge of weeds in the area.

COGCC Decision: Approved pending re-inspection

COGCC Representative: The attached weed plan appears to provide mostly non-pertinent information regarding Wapiti's ongoing weed control plan. It is unlikely that performing weed control once annually will be sufficient. As a condition of approval of the weed control plan, Wapiti must: 1. Monitor and conduct weed control throughout the growing season. 2. Perform noxious weed control in the early Summer and Fall as recommended by the contractor. 3. Perform Integrated Weed Management such as but not limited to physical, cultural, and chemical control. Submittal of the Weed Control plan does not preclude enforcement action. Ongoing inspections will be performed to evaluate compliance of Rule 1003.f.

2  CA# 128368

Corrective Action: Comply with Rule 1003.f.
Control noxious weeds.

Date: 07/10/2019

Response: CA COMPLETED

Date of Completion: 08/01/2019

Operator Comment: Weedds have been sprayed on the pad, along the road right of way and the ones in the middle of the horse shoe lease road.

COGCC Decision: **Not Approved**

COGCC Representative: Inspection performed on 8/23/2019 documented noxious weeds not adequately controlled.

3  CA# 128369

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 07/17/2019

Response: CA COMPLETED

Date of Completion: 08/08/2019

Operator Comment: Additional rock check have been installed and culverts cleaned and rocked.

COGCC Decision: Approved

COGCC Representative: Ongoing maintenance is required.

OPERATOR COMMENT AND SUBMITTAL

Comment: We installed additional rock rip/rap where the water runs off of the pad. Cleaned culverts and added rock checks. Attached the weed plan and sprayed the weeds off the pad in horse shoe shape created by the lease road to the pad.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Randy Madison

Signed: _____

Title: HSE Specialist

Date: 8/20/2019 1:45:09 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402150683	FIR RESOLUTION SUBMITTED
402150692	Photo of Rock rip/rap at the end of Culvert
402150695	Wapiti Weed Plan
402150696	Photo of Culvert cleaned with little soil disturbance
402150702	Photo of rock installed off of Pad to prevent erosion
402150706	Photo of Weeds Dying

Total Attach: 6 Files