

Inspection Photos
Location Name: Dwinell 1
Location ID: 324591



**Photo 1. Overview of location taken facing southeast.
Former landfarm area in center of photo.**



Photo 2. Example of trash and debris on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dwinell 1
Location ID: 324591



Photo 3. Debris on wellhead gauge.



Photo 4. Overview of wellhead area.



Inspection Photos
Location Name: Dwinell 1
Location ID: 324591



Photo 5. Pit with noxious and annual weeds.



Photo 6. Noxious weeds.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dwinell 1
Location ID: 324591



Photo 7. Trash and debris on location.



Photo 8. Incomplete tank labels, no NFPA diamond.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources