

Getty Pan American 29

API: 05-103-08252

Inspection: 679705591



40.07688, -108.84524, 5125.7ft, 280°
09/26/2019 01:39:09 PM

Photo 1. Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Getty Pan American 29

API: 05-103-08252

Inspection: 679705591



Photo 2. 10' wide break in location berm. NE corner.



Photo 3. 5' wide break in location berm. NE corner.

Getty Pan American 29
API: 05-103-08252
Inspection: 679705591



Photo 4. Animal burrow hole inside of west tank berm.



Photo 5. 1' wide low spot in berm SW corner.