

Inspection Photos
Operator: Highpoint Operating
Location/API #: 083-06651
Date: 9-18-2019



Photo 1. View of the former well pad from the southern edge facing center. Well pad is recontoured and appears to have been cultivated this year.



Photo 2. View of the southern project area from the approx. southern edge facing westward.



Photo 3. View of former access road facing southward.



Photo 4. View of reference area in cultivated wheat field. Vegetation will need to be assessed when actively growing.