

Inspection Photos
Location Name: Ptasynski 5
Location ID: 312975



Photo 1. Overview of location taken facing west.



Photo 2. Weeds on and in berm.



Inspection Photos
Location Name: Ptasynski 5
Location ID: 312975



Photo 3. Pit 1 of 2.



Photo 4. Pit 2 of 2.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources