

Inspection Photos

Loc#324427

Operator: Chevron

Inspection Number: 692401373

Inspection Date: 8/21/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location to North; Areas no longer needed for Use have not been Reclaimed.

August 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron SKR Loc#324427



Photo#2:
2009 aerial of Location.

August 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron SKR Loc#324427



Photo#3:
2017 aerial of Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron SKR Loc#324427