

Inspection Photos

API: 05-071-07986

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/27/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07986 | Date: 9/27/2019

Inspection Photos



Photo 1. There is a dripping water leak at the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07986 | Date: 9/27/2019

Inspection Photos



Photo 2. The berm around the tank is worn down and appears to be inadequate to contain spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07986 | Date: 9/27/2019

Inspection Photos



Photo 3. There is a cage fencing that appears to be unused.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07986 | Date: 9/27/2019