

Inspection Photos

API: 05-071-06356

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/27/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06356 | Date: 9/27/2019

Inspection Photos



Photo 1. Facing south toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06356 | Date: 9/27/2019

Inspection Photos



Photo 2. It appears the southwest disturbance area was reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06356 | Date: 9/27/2019

Inspection Photos



Photo 3. Operator name has not been updated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06356 | Date: 9/27/2019