

Inspection Photos

09/27/2019

Operator: PETRO-CANADA RESOURCES (USA)

INC - 72085

Location ID: 311698

Adams County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos

Operator Name: PETRO-CANADA RESOURCES (USA) INC - 72085

Location ID: 311698



Photo 1: Photo taken from the reclaimed access road. Additional revegetation activities appear to be needed.

Inspection Photos

Operator Name: PETRO-CANADA RESOURCES (USA) INC - 72085

Location ID: 311698



Photo 1: Photo taken from the south end of the disturbed drainage, facing northwest. Recent mowing operations evident, however, vegetation on the location is predominantly undesirable weedy plant species with little to no desirable perennial plant germination evident.



Photo 2: Photo taken from the south end of the disturbed drainage, facing northeast. Recent mowing operations evident, however, vegetation on the location is predominantly undesirable weedy plant species with little to no desirable perennial plant germination evident.