

Inspection Photos
Location Name: BOWMAN 41-21
API#: 05-071-06230
INSP. #: 695101445



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN



Inspection Photos
Location Name: BOWMAN 41-21
API#: 05-071-06230
INSP. #: 695101445



PHOTO 3: OILY STAINED SOIL NEAR ENGINE SKID. Properly treat or dispose of oily waste in accordance with 907.e. CA DATE 11-1-19



PHOTO 4: TRASH NEAR ENGINE SKID. REMOVE TRASH COMPLY WITH RULE 603.f. CA DATE 11-1-19

Inspection Photos
Location Name: BOWMAN 41-21
API#: 05-071-06230
INSP. #: 695101445



PHOTO 5: OILY STAINED TRASH NEAR ENGINE SKID. REMOVE TRASH COMPLY WITH 603.f. CA DATE 11-1-19



PHOTO 6: UNUSED EQUIPMENT. REMOVE UNUSED EQUIPMENT COMPLY WITH RULE 603.f. CA DATE 11-1-19