



WELL SITE INSPECTION FORM

WELL NAME Iliff-Ertle 18-1
OPERATOR Lasmo Energy
LOCATION SE NW 18-9N-52W
FIELD Hamil Ranch

API NUMBER 05 - -
PERMIT NUMBER _____
COUNTY Logan
INSPECTOR SP

AL/PA/DA INSPECTION RESULTS:

WELL STATUS:

PASS(Y) _____ FAIL(N) _____ DATE _____ FN _____ FD _____ WO _____

=====

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____
CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____
RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION 1/26/89

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____
DRILLING PITS: CLOSED ☒ OPEN _____ WELLHEAD SYSTEM INSTALLED ☒
TANK ID: YES ☒ NO _____ NA _____ WELL SIGN: YES ☒ NO _____
SKIM PIT: ☒ gal TANKS: (2) 300 bbls
EQUIPMENT Pump jack on well
BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____
METER RUN: YES _____ NO ☒ WELL STATUS: PR _____ TA _____ SI ☒ WELL CAT 3-d

AL/PA/DA INSPECTION

DATE PLUGGED: _____ DATE PERMIT EXPIRED: _____
HOLE PLUGGED: YES _____ NO _____ PITS BACKFILLED: YES _____ NO _____
MATERIAL BURIED: YES _____ NO _____ NA _____ SITE CLEAN: YES _____ NO _____
BOND RELEASE OK: YES _____ NO _____ FED _____ HOLE MARKER: YES _____ NO _____

DATE OF SAFETY/STATUS INSPECTION _____

COMMENTS * 15' x 15' skim pit
40' x 40' w 1/2 full
15' x 40'